

From: energy_manchester
Sent: 11 December 2017 11:35
To: Chris Bartlett
Subject: RE: Question

Chris

As requested, please find attached an updated Figure 4 with the correct fence height (2m).

I can confirm that the depth of the existing borehole is 820m. The extent of the lateral well is 520m.

On the HGV movements I can confirm that paragraph 3.7.1 of the Planning Statement is incorrect. There will be HGV movements during the flow test and pressure monitoring stages and these will be in line with the (revised) Table 8.1 of the Environmental Report. I can also confirm that all HGV movements during the flow test and pressure monitoring stages will take place during standard working hours. The only potential exception to this is if any essential repairs to plant and equipment on site need to be undertaken.

I trust that the above response adequately responds to all of the outstanding queries. Please can you advise when a copy of the draft Planning Committee Report will be available to review?

Regards, Stephen