Comment for planning application WSCC/004/20

Address OLD SCHOOL STUDIO, HAMMERWOOD ROAD, HAMMERWOOD ROAD, EAST GRINSTEAD, RH19 3RX Type of Comments Although this proposal is proposed as the necessary remedial work to protect the environment from an obviously poorly executed previous tipping on this "farm" site, evidently then driven by economic gain, it appears that this "remedial work" would also be for economic gain to the owner of the site. Clearly waste dumping should never haver been licensed for this site, and the arrangements then made were evidently not appropriate to ensuring the long term safety of the surrounding areas. Firstly it seems quesionable whether there is in fact a hazard that requires this type of remedial action. The evidence for leaching ground water - likely to be the most concerning feature, is sparse. This could be addressed perhaps by ensuring drainage routes to a prepared receptor, and pumping this for safe disposal. It seems unlikely that there is a major hazard form gaseous components. If these are being produced, the pressure build-up will result in them venting what ever capping is used. Indeed the proposal areas with little inconvenience to local people. He could also not put animals on areas where land has subsided - after all it was the owner who previously used the land as land-fill. The traffic report (road safety audit) is minimalistic in the extreme. It appears to only consider road movements at the point of entry onto the site. The fact that the road is extremely narrow with poor site lines, serves a number of educational establishments, Care Homes and very many residential households towards East Grinstead, as well as establishments quere Hoathly as well as other villages, to East Grinstead, us well as establishments quere Hoathly as well as other villages, to East Grinstead, se well as establishments quere and that required will be extremely detrimental to the AONB. Such as Class the road does not have pavements, but is used by pedestrians and many cyclist. The propsal is in an Area of Outstanding Natural Beauty,	Application number	WSCC/004/20
Type of Consect or being in an extra being first of the provided for the environment from an obviously poorly executed previous tipping on this "farm" site, evidently then driven by economic gain, it appears that this "remedial work" would also be for economic gain to the owner of the site. Clearly waste dumping should never haver been licensed for this site, and the arrangements then made were evidently not appropriate to ensuring the long term safety of the surrounding areas. Firstly it seems quesionable whether there is in fact a hazard that requires this type of remedial action. The evidence for leaching ground water - likely to be the most concerning feature, is sparse. This could be addressed perhaps by ensuring drainage routes to a prepared receptor, and pumping this for safe disposal. It seems unlikely that there is a major hazard form gaseous components. If these are being produced, the pressure build-up will result in them venting what ever capping is used. Indeed the proposal appears to be providing for such vents. The only actual hazards appear to be visual evidence of waste such as plastics, and the uneven land surface. The land owner could no doubt re-cover these eroded areas with little inconvenience to local people. He could also not put animals on areas where land has subsided - after all it was the owner who previously used the land as land-fill. The traffic report (road safety audit) is minimalistic in the extreme. It appears to only consider road movements at the point of entry onto the site. The fact that the road is extremely narrow with poor site lines, serves a number of educational establishments, care Homes and very many residential households towards East Grinstead, as well as establishments generating heavy traffic, such as Standen, Saint Hill Manor; and serves as a route for traffic from Sharpthorne and Weat Hoathly as well as other villages, to East Grinstead, is entirely ignored. Also the road does not have pavements, but is used by pedestrians and many cyclists. The proposal is i	Name	Martin Leach
CommentAlthough this proposal is proposed as the necessary remedial work to protect the environment from an obviously poorly executed previous tipping on this "farm" site, evidently then driven by economic gain, it appears that this "remedial work" would also be for economic gain to the owner of the site. Clearly waste dumping should never haver been licensed for this site, and the arrangements then made were 	Address	OLD SCHOOL STUDIO, HAMMERWOOD ROAD, HAMMERWOOD ROAD, EAST GRINSTEAD, RH19 3RX
 abidgin and proposed by the previous tipping on this "farm" site, evidently then driven by economic gain, it appears that this "remedial work" would also be for economic gain to the owner of the site. Clearly waste dumping should never haver been licensed for this site, and the arrangements then made were evidently not appropriate to ensuring the long term safety of the surrounding areas. Firstly it seems quesionable whether there is in fact a hazard that requires this type of remedial action. The evidence for leaching ground water - likely to be the most concerning feature, is sparse. This could be addressed perhaps by ensuring drainage routes to a prepared receptor, and pumping this for safe disposal. It seems unlikely that there is a major hazard form gaseous components. If these are being produced, the pressure build-up will result in them venting what ever capping is used. Indeed the proposal appears to be providing for such vents. The only actual hazards appear to be visual evidence of waste such as plastics, and the uneven land surface. The land owner could no doubt re-cover these eroded areas with little inconvenience to local people. He could also not put animals on areas where land has subsided - after all it was the owner who previously used the land as land-fill. The traffic report (road safety audit) is minimalistic in the extreme. It appears to only consider road movements at the point of entry onto the site. The fact that the road is extremely narrow with poor site lines, serves a number of educational establishments, Care Homes and very many residential households towards East Grinstead, as well as establishmest generating heavy traffic, such as Standen, Saint Hill Manor; and serves as a route for traffic from Sharpthorne and Weat Hoathly as well as other villages, to East Grinstead, is entirely ignored. Also the road does not have pavements, but is used by pedestrians and many cyclists. The proposal is in an Area of Outstanding Natural Beauty, and will not enhance or conserve the b	Type of Comment	Objection
22/02/2020 20:43:40	Comments	obviously poorly executed previous tipping on this "farm" site, evidently then driven by economic gain, it appears that this "remedial work" would also be for economic gain to the owner of the site. Clearly waste dumping should never haver been licensed for this site, and the arrangements then made were evidently not appropriate to ensuring the long term safety of the surrounding areas. Firstly it seems quesionable whether there is in fact a hazard that requires this type of remedial action. The evidence for leaching ground water - likely to be the most concerning feature, is sparse. This could be addressed perhaps by ensuring drainage routes to a prepared receptor, and pumping this for safe disposal. It seems unlikely that there is a major hazard form gaseous components. If these are being produced, the pressure build-up will result in them venting what ever capping is used. Indeed the proposal appears to be providing for such vents. The only actual hazards appear to be visual evidence of waste such as plastics, and the uneven land surface. The land owner could no doubt re-cover these eroded areas with little inconvenience to local people. He could also not put animals on areas where land has subsided - after all it was the owner who previously used the land as land-fill. The traffic report (road safety audit) is minimalistic in the extreme. It appears to only consider road movements at the point of entry onto the site. The fact that the road is extremely narrow with poor site lines, serves a number of educational establishments, Care Homes and very many residential households towards East Grinstead, is entirely ignored. Also the road does not have pavements, but is used by pedestrians and many cyclists. The proposal is in an Area of Outstanding Natural Beauty, and will not enhance or conserve the beauty in any way. The heavy work and traffic involved will be extremely detrimental to the AONB. Such scale of work, especially juxtopositioned with Standen and using the same access route from East Grinstead, which
Attachments	Received	22/02/2020 20:49:46
	Attachments	